

General Environmental Incident Summary

Incident: 3366 **Date/Time Notice:** 6/25/2014 15:22 **DEM Incident No:**

Responsible Party: Marathon

Date Incident: 6/25/2014 **Time Incident:** 18:00 **Duration:**

County: Slope **Twp:** 135 **Rng:** 99 **Sec:** 27 **Qtr:**

Lat: 46.48187 **Long:** -103.10090 **Method:** Derived from Twn Rng

Location Description: Powell 31-27 TH

- * From the Marathon office, travel south on Hwy 22 ~ 4 miles to Interstate 94.
- * Turn right (west), travel ~ 22 miles to Belfield (Hwy 85).
- * Turn left (south), travel ~ 25.2 miles Hwy 21 (4 miles past the Rundle Trust location).
- * Turn left (east), travel 4 miles to Hwy 6.
- * Turn right(south), travel 4 miles to unmarked road.
- * Turn left (east), travel 1 mile to lease road.
- * Turn left and follow lease road to location.

Submitted By: Ashley Schaper

Affiliation:

Address: 3172 HWY 22 N

City: Dickinson

State: ND

Zip: 58601

Received By:

Contact Person: Ashley Schaper
3172 HWY 22 N
Dickinson, ND 58601

Distance Nearest Occupied Building:

Release Contained: No

Type of Incident: valve

Description of Released Contaminant: Brine Water

Volume Spilled: 15.00 barrels

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Valves were leaking this caused 15 bbls of brine water to be released. 9 bbls came into contact with unprotected ground on location, 6 bbls was in containment on location. No fluids left location

Risk Evaluation:

No immediate Risks

of Fatalities:

of Injuries:

Affected Medium: 03 - soil

Potential Environmental Impacts:

Minimal potential environmental impacts

Action Taken or Planned:

Soil was cleaned up and will be taken to an approved disposal. Fluid was cleaned up with Vac truck.

Wastes Disposal Location: Approved landfill

Agencies Involved:

Updates

Date: 6/25/2014

Status: Reviewed; O&G Lead

Staff: Roberts, Kris

Updated Volume:

Notes:

Release, due to a leaking valve on location, remained on location according to the report. NDIC retains oversight. Report forwarded to NDIC.